



## HUB UNITS 2

| Unit No.        | Bearing NO. |                   |             | Dimensions(mm) |       |       |
|-----------------|-------------|-------------------|-------------|----------------|-------|-------|
|                 | IRB         | SKF               | SNR         | d              | D     | B/C   |
| DAC251280058    | 8574        | BAFB446595E       |             | 25             | 128   | 58    |
| DAC2512800635   | 8578        | BAFB447302AA      |             | 25             | 128   | 63.5  |
| DAC251330043    | 8623        |                   | TGB12096S21 | 25             | 133   | 43    |
| DAC25133043A    | 8598        |                   | TGB12095S25 | 25             | 133   | 43    |
| DAC25130043B    | 8602        |                   | TGB12096S22 | 25             | 133   | 43    |
| DAC251340061    | 8584        |                   |             | 25             | 134   | 61    |
| DAC281340061    | 8585        |                   |             | 28             | 134   | 61    |
| DAC301200052    | 8619        |                   | TGB40189    | 30             | 120   | 52    |
| DAC301200052A   | 8620        |                   | TGB40189S01 | 30             | 120   | 52    |
| DAC3012000685   | 8626        | BAFB446912AC      |             | 30             | 120   | 68.5  |
| DAC3012000685A  | 8627        | BAFB446912AC/W1   |             | 30             | 120   | 68.5  |
| DAC301310065    | 8608        | BAFB663903        |             | 30             | 131   | 65    |
| DAC301310065A   | 8625        | BAFB633903B       |             | 30             | 131   | 65    |
| DAC301310065B   | 8607        | BAFB633872A       |             | 30             | 131   | 65    |
| DAC321280059    | 8605        | BAFB446628BA      |             | 32             | 128   | 59    |
| DAC3212910058   | 8592        | BAFB446451EB      |             | 32             | 129.1 | 58    |
| DAC351280065    | 8617        | BAFB633938        |             | 35             | 128   | 65    |
| DAC351280065A   | 8612        | BAFB633755C       |             | 35             | 128   | 65    |
| DAC351360084    | 8616        | BAFB446935AB      |             | 35             | 136   | 84    |
| DAC351360084A   | 8615        | BAFB446930AB      |             | 35             | 136   | 84    |
| DAC3513630075   | 8544        | BA2B243592D/VU028 |             | 35             | 136.3 | 75    |
| DAC40980046     | 8596        | BAFB636044B       |             | 40             | 98    | 46    |
| DAC401080032/17 | IR-8048     | BAFB445533A       | TGB10872S02 | 39.98          | 108   | 17/32 |
| DAC4011000324   | IR-8067     | BAFB442377D       |             | 40             | 110   | 32.4  |
| DAC5011600338   | IR-8113     | BAFB441696R       |             | 50             | 116   | 33.8  |
| DAC5011600364   | IR8068      | BAFB              | TGB10894S03 | 50             | 116   | 36.4  |
| DAC5011600338A  | 8519        | 441696M           |             | 50             | 116   | 33.8  |

Changzhi TEBearing Corp., Ltd.

1 Huafeng North Road Changzhi city, Shanxi province, China

**Tel: +86 355 3022969**

**Mobile: +86 18635527655**

**Skype:shawwinliu**

**Email: [tebearing@aliyun.com](mailto:tebearing@aliyun.com)**

**[shawwin@tebearing.com](mailto:shawwin@tebearing.com)**

**[www.tebearing.com](http://www.tebearing.com)**

**<http://te-bearing.en.alibaba.com>**

